

## **AMS-02 Electronics Non-Conformance Report**

- 1. Subsystem:** UPPER T-Crate
- 2. Part Name:** Upper T-Crate Main Wall Lower
- 3. Revision:** 24-AMS-110-03.12 Rev.B
- 4. Production:** FM/FS
- 5. Production Date:** 2007
- 6. Producer:** CSIST
- 5. Quantity:** 5
- 6. Serial Numbers:**
- 7. Non Conformance:** Cable Outlets too small
- 8. Solution:** CGS will issue an ECO (ECO-00116),  
CSIST reworked the mechanics, acc. To related  
ECO see App. A
- 9. Signature:** Daniel Haas
- 10. Date of Report:** 30 July 2007

## **AMS-02 Electronics Non-Conformance Report**

- 1. Subsystem:** LOWER T-Crate
- 2. Part Name:** Lower T-Crate Main Wall Lower
- 3. Revision:** 24-AMS-110-03.02 Rev.A
- 4. Production:** FM/FS
- 5. Production Date:**
- 6. Producer:** CSIST
- 5. Quantity:** 5
- 6. Serial Numbers:**
- 7. Non Conformance:** Cable Outlets too small
- 8. Solution:** CGS will issue an ECO (ECO-00115),  
CSIST reworked the mechanics, acc. To related  
ECO see App. A
- 9. Signature:** Daniel Haas
- 10. Date of Report:** 30 July 2007

## **AMS-02 Electronics Non-Conformance Report**

- 1. Subsystem:** T-Crate
- 2. Part Name:** TDR2
- 3. Revision:**
- 4. Production:** FM/FS
- 5. Production Date:**
- 6. Producer:** CSIST
- 5. Quantity:** 1
- 6. Serial Numbers:** 95016F
- 7. Non Conformance:** short on Jumper Side B (after coating)
- 8. Solution:** coating locally removed, short repaired, coating done again locally.
- 9. Signature:** Daniel Haas
- 10. Date of Report:** 30-6-2007

## **AMS-02 Electronics Non-Conformance Report**

- 1. Subsystem:** T-Crate
- 2. Part Name:** TDR2
- 3. Revision:**
- 4. Production:** FM/FS
- 5. Production Date:**
- 6. Producer:** CSIST
- 5. Quantity:** 1
- 6. Serial Numbers:** 95018F
- 7. Non Conformance:** Actel non-working (before coating)
- 8. Solution:** Actel replaced
- 9. Signature:** Daniel Haas
- 10. Date of Report:** 30-6-2007

## **AMS-02 Electronics Non-Conformance Report**

- 1. Subsystem:** T-Crate
- 2. Part Name:** TDR2
- 3. Revision:**
- 4. Production:** FM/FS
- 5. Production Date:**
- 6. Producer:** CSIST
- 5. Quantity:** 1
- 6. Serial Numbers:** 95038F
- 7. Non Conformance:** SSF -5.6 S, Side B not working
- 8. Solution:** SSF has been replaced
- 9. Signature:** Daniel Haas
- 10. Date of Report:** 30-6-2007

## **AMS-02 Electronics Non-Conformance Report**

- 1. Subsystem:** T-Crate
- 2. Part Name:** TDR2
- 3. Revision:**
- 4. Production:** FM/FS
- 5. Production Date:**
- 6. Producer:** CSIST
- 5. Quantity:** 1
- 6. Serial Numbers:** 95041F
- 7. Non Conformance:** short on Actel pins
- 8. Solution:** pins have been cleaned
- 9. Signature:** Daniel Haas
- 10. Date of Report:** 30-6-2007

## **AMS-02 Electronics Non-Conformance Report**

- 1. Subsystem:** T-Crate
- 2. Part Name:** TDR2
- 3. Revision:**
- 4. Production:** FM/FS
- 5. Production Date:**
- 6. Producer:** CSIST
- 5. Quantity:** 1
- 6. Serial Numbers:** 95063F
- 7. Non Conformance:** short on 5.6 V S, Side A
- 8. Solution:** short origin has been identified, and fixed
- 9. Signature:** Daniel Haas
- 10. Date of Report:** 30-6-2007

## **AMS-02 Electronics Non-Conformance Report**

- 1. Subsystem:** T-Crate
- 2. Part Name:** TDR2
- 3. Revision:**
- 4. Production:** FM/FS
- 5. Production Date:**
- 6. Producer:** CSIST
- 5. Quantity:** 1
- 6. Serial Numbers:** 95101F
- 7. Non Conformance:** +5.6 V presents incorrect behaviour, Side A
- 8. Solution:** ACTEL side A has been replaced
- 9. Signature:** Daniel Haas
- 10. Date of Report:** 30-6-2007